



Forane® 507

Pressure-Temperature Chart

Saturation
Temperature Pressure
[°F] [psig]

-50	1.1
-45	3.3
-40	5.7
-35	8.3
-30	11.2
-25	14.3
-20	17.8
-15	21.6
-10	25.7
-5	30.1
0	34.9
5	40.2
10	45.8
15	51.8
20	58.3
25	65.3
30	72.8
35	80.8
40	89.3
45	98.4
50	108.1
55	118.1
60	129.4
65	141.1
70	153.4
75	166.4
80	180.2
85	194.8
90	210.1
95	226.3
100	243.4
105	261.3
110	280.2
115	300.0
120	320.8
125	342.6
130	365.5
135	389.4
140	414.5
145	440.7
150	468.1

Red numerals = inches Hg below 1 atm